

REFROIDISSEMENT - COOLING



HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
CHRYSLER					
9.9	1979-97	Tous / All	700-140	---	---
10	1974-78	Tous / All	700-140	---	---
12	1979	Tous / All	700-140	---	---
15	1974-97	Tous / All	700-140	---	---
20	1973-78	Tous / All	700-140	---	---
20	1979-82	Tous / All	700-135	---	---
25	1973-78	Tous / All	700-140	---	---
25	1996-98	E127700-E344999	700-225	---	---
30	1980-82	Tous / All	700-135	---	---
35	350-355 HA,HB, HC,HD	---	700-120	---	---
35	356/357 HA,HB	---	700-120	---	---
35	350 HF	---	700-120	---	---
35	351 HF	---	700-120	---	---
35	352/353H2P/H9L, 353HOM,HIN	---	700-120	---	---
35	354HF	---	700-120	---	---
35	355HF	---	700-120	---	---
35	356HD	---	700-120	---	---
35	357HD	---	700-120	---	---
40/50	1995-99	E093700-E369299	700-225	---	---
45	450-457HA,HC,HD 458/459HA,HB	---	700-120	---	---
55	551HA	---	700-130	---	---
55	554-559HA,HD	---	700-120	---	---
70	709HOAN,49A	---	700-130	---	---
70	T700H9A,706/ 707HA,HC,HD,HE	---	700-130	---	---
75	T750H9A,757H9E, P.S759H9A	---	700-130	---	---
75	1996-98	E138600-E345999	700-230	---	---
85	856/857HA,HC,HD	---	700-130	---	---
90	1991A,B,CD-1992C	E000001-E039023	700-205	---	---
90	1992-94	E039024-E093699	700-205	---	---
90	1995-97	E2093700 & +	700-155	---	---
90L-Drive	1991	---	700-205	---	---
CHRYSLER					
105	1056/1057HA-HE, 1058HA-HC	---	700-130	---	---
120	1206/1207HA-HE, 1208HA-HC	---	700-130	---	---
135	1358HA-HC	---	700-130	---	---
150	1508HA	---	700-130	---	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
FORCE					
9.9-15	1979-97	(Tous/All)	700-140	---	---
20	1973-78	(Tous/All)	700-140	---	---
20	1979-82	(Tous/All)	700-135	---	---
25	1973-78	(Tous/All)	700-140	---	---
25/40/50	1995-99	---	700-145	---	---
30	1973-82	(Tous/All)	700-135	---	---
35	1976-87	(Tous/All)	700-135	---	---
70-75	1991-98	(Tous/All)	700-230	---	---
75	1999 & +	---	700-155	---	---
85	1975-88	(Tous/All)	700-115	---	---
85	1989	D,F,G,H	700-205	---	---
85	1989	L-Drive (Tous/All)	700-205	---	---
90	1990	A,B,C	700-205	---	---
90	1990-94	L-Drive A,C	700-205	---	---
90/120	1995-97	Sport Jet	700-155	---	---
120	1990	(Tous/All)	700-205	---	---
120	1990	L-Drive (Tous/All)	700-205	---	---
125	1981-88	A,B,C	700-115	---	---
125	1989	D,E	700-205	---	---
150	1989 & +	(Tous/All)	700-205	---	---
HONDA					
5	---	---	700-160	---	---
7.5	---	---	700-160	---	---
8	---	---	700-160	---	---
BF8D/9.9D	---	---	700-155	---	---
9.9	---	---	700-170	---	---
9.9D	---	---	700-155	---	---
10	---	---	700-160	---	---
BF15	---	---	700-165	---	---
15	---	---	700-170	---	---
20	---	---	700-180	---	---
25	---	---	700-180	---	---
30	---	---	700-180	---	---
35	---	---	700-175	---	---
40	---	---	700-175	---	---
45	---	---	700-175	---	---
50	---	---	700-175	---	---
75	---	---	700-185	---	---
BF75-90	1996-98	---	700-155	---	---
115	---	---	700-185	---	---
130	---	---	700-185	---	---
BF135-225	---	---	700-150	---	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
MARINER					
8A(M), ML	655	000000-300101&+	700-403	---	---
8B(M),ML	677	000101-300101&+	700-403	---	---
15A(M),ML	651	3000100 & -	700-403	---	---
20C(E),(EL),(M),(ML)	6A9	250819 & -	700-410	---	750-410
20C(E),(EL),(M),(ML)	6A9	250820 & +	700-410	---	750-411
25C(E),(EL),(M),(ML)	695	014870 & -	700-410	---	750-410
25C(E),(EL),(M),(ML)	695	014871 & +	700-410	---	750-411
28	664	(Tous/All)	700-410	---	---
30	689	(Tous/All)	700-410	---	---
30A(E),(EL),(M),(ML)	689	014805 & -	700-410	---	750-410
30A(E),(EL),(M),(ML)	689	105325 & +	700-410	---	750-411
MERCURY					
3.5	---	6202173 & +	700-215	---	---
3.6	---	5404651 & +	700-215	---	---
4	---	2498136-4107219	700-210	---	---
40/4	2 Cyl.	5589202 & +	700-215	---	---
4	Made in USA	5595532-9075838	700-215	---	---
4	Made in USA	5595532-9075838	700-210	---	---
4.5	---	4107220-5595531	700-210	---	---
4.5	---	5595532 & +	700-215	---	---
4.5	---	5595532 & +	700-210	---	---
5	---	338136-574128	700-435	---	---
6	---	888005-1916138	700-435	---	---
6	---	1916139-2529894	700-210	---	---
7.5	---	2529895-3274632	700-210	---	---
7.5	---	4131610-5226934	700-210	---	---
7.5	---	5206650 & +	700-210	---	---
110 (9.8)	---	1865779-4126459	700-210	---	---
110 (9.8)	---	4126460-5206549	700-210	---	---
9.8	---	1470349-1865778	700-435	---	---
9.8	---	1865779-5206549	700-210	---	---
9.8	---	5206550 & +	700-210	---	---
18	---	5837437-6416712	700-225	---	---
20	---	2827677-6443972	700-203	---	---
20XD	---	6443973 & +	700-225	---	---
25	3 Cyl.	E268781 & +	700-225	---	---
25XD	---	6443973 & +	700-225	---	---
30	---	1271884-1448139	700-225	---	---
30 Jet	---	C159200-G589999	700-225	---	---
30 Jet	---	G755000 & +	700-225	---	---
30	2 Cyl.	G053314 & +	700-225	---	---
35	---	1217222-1448139	700-200	---	---
35	---	1571114-6445652	700-200	---	---
35	---	6445653 & +	700-200	---	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
MERCURY					
40	---	1224481-1476509	700-200	---	---
40	---	2874704-4362214	700-200	---	---
40	---	4362215-4860102	700-200	---	---
40	2 Cyl.	4862103-6445653	700-200	---	---
40	2 Cyl.	OG053314 & +	700-225	---	---
40	3 Cyl.	OG531301 & +	700-225	---	---
40	4 Cyl.	OC159200 & +	700-200	---	---
40	4 Stroke Std.	OG231123-OG760299	700-225	---	---
40	4 Stroke 2:1 ratio	OG760300-OT408999	700-225	---	---
40	4 Stroke 4 Cyl. 1.83:1 ratio	OT228405 & +	700-230	---	---
40	4 Stroke Big Foot & 2.31:1 ratio	OT228405 & +	700-155	725-155	750-155
40	4 Stroke 4 Cyl. 2.31:1 ratio	OT228405 & +	700-155	725-155	---
40	EFI 4 Stroke 1.83:1 ratio	OT409000 & +	700-230	---	---
40	EFI 4 Stroke 2.31:1 ratio	OT409000 & +	700-155	725-155	---
40	4 Stroke Big Foot & 2.31:1 ratio	G231123 & +	700-155	725-155	---
45	---	1279685-1476509	700-200	---	---
45	---	5531630 & +	700-200	---	---
45	Jet 3 Cyl.	D000750 & +	700-230	---	---
45	4 Stroke Std. Bodensee	OG231123 & +	700-225	---	---
45	4 Stroke Big Foot Bodensee	OG231123 & +	700-155	---	---
50	---	1421113-1521913	700-200	---	---
50	---	1521914-2514918	700-200	---	---
50	---	2514919-4357639	700-200	---	---
50	---	4357640-4962055	700-200	---	---
50	4 Cyl.	4962056 & +	700-200	---	---
50	3 Cyl.	6428681-OD000749	700-200	---	---
50	3 Cyl.	OD000750-OG589999	700-230	---	---
50	3 Cyl.	OG590000 & +	700-225	---	---
50	4 Stroke Std.	OG231123 & +	700-225	---	---
50	4 Stroke 4 Cyl. 1.83:1 ratio	OT178500 & +	700-230	---	---
50	4 Stroke 4Cyl. 2.31:1 ratio	OT178500 & +	700-155	725-155	---
50	EFI 4 Stroke 1.83:1 ratio	OT409000 & +	700-230	---	---
50	EFI 4 Stroke 2.31:1 ratio	OT409000 & +	700-155	725-155	---
50	4 Stroke Big Foot	OG231123 & +	700-155	725-156	---
55	3 Cyl.	OD000750 & +	700-230	---	---
60	---	6428681-OD000749	700-200	---	---
60	Sea Pro / Marathon / Big Foot	OD000750 & +	700-234	---	---
60	3 Cyl.	OD000750 & +	700-230	---	---
60	4 Stroke Std.	OT178500 & +	700-230	---	---
60	4 Stroke Big Foot	OT178500 & +	700-155	725-155	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
MERCURY					
65	4 Cyl.	1542745-3293183	700-205	725-157	---
65	3 Cyl.	3283184-4382056	700-205	---	---
65	3 Cyl.	4382057-4571651	700-200	---	---
65	Jet	OD283222 & +	700-155	725-155	---
70	---	1413611-1566239	700-205	---	---
70	3 Cyl.	4571652-4977156	700-200	---	---
70	---	4977157-OB110053	700-200	---	---
70	---	OB110054 & +	700-155	725-155	---
75	4 Cyl.	6432901 & +	700-200	725-157	750-157
75	3 Cyl.	A996142-OC221999	700-155	725-155	---
75	3 Cyl. Impeller I.D..456	OC222000 & +	700-155	725-155	---
75	w/o insulator on	OC222000 & +	700-155	725-155	---
75	4 Stroke	OG960500 & +	700-155	725-155	---
80	---	1335468-3493912	700-200	725-157	---
80	4 Cyl.	4831999-6432900	700-155	725-157	750-157
80	3 Cyl.	A996142 & +	700-155	725-155	---
80	Jet	OD28322 & +	700-155	725-155	---
85	---	1460999-4841998	700-205	725-157	---
85	4 Cyl.	4590512 & +	700-205	725-157	750-157
90	---	1766824-1869775	700-205	725-157	---
90	6 Cyl.	4845301 & +	700-205	725-157	750-157
90	3 Cyl.	OA996142 & +	700-205	725-155	---
90	3 Cyl. w/o insulator on housing bolts	AO996142 & +	700-155	725-155	---
90	4 Stroke	OG9605000 & +	700-155	725-155	---
95	---	1869776-2318585	700-205	725-157	---
100	6 Cyl.	1464949-3253111	700-205	725-157	---
100	4 Cyl.	OB209468 & +	700-155	725-155	---
105	Jet	OD182000 & +	700-205	---	---
110	---	1870204-2314955	700-205	725-157	---
115	---	2836019 & +	700-155	725-157	---
115	6 Cyl.	4694237 & +	700-205	725-157	750-157
115	4 Cyl.	OB209468 & +	700-155	725-155	750-155
115	4 Stroke	OT178500 & +	700-155	725-155	---
125	---	2314956-3253111	700-205	725-157	---
125	4 Cyl.	OD283222 & +	700-155	725-155	750-155
135	V6	A904646 & +	700-205	725-157	---
140	---	3293234-3502805	700-205	725-157	750-157
140	Jet	4865678-5327662	700-205	725-157	750-157
150	---	3502806-4121434	700-205	725-157	---
150	---	4121435-4868647	700-205	725-157	750-157
150	---	A904645 & -	700-205	725-157	---
150	---	A904646 & +	700-205	725-157	---
175	---	4301235-6618750	700-205	725-157	750-157
175	---	6618751 & -	700-205	725-157	---
175	---	6618751 & +	700-205	725-157	---
200	---	6625220 & -	700-205	725-157	---
200	---	6625221 & +	700-205	725-157	---
V-200	DFI (3.OL)	OG386496 & +	700-155	725-155	750-155
220	---	OB117316 & +	700-205	725-157	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
MERCURY					
225	---	5625028 & +	700-205	725-157	---
V-225	(3.0L) Carb & EFI	OD280813 & +	700-155	725-155	750-155
V-225	DFI	OG590000 & +	700-155	725-155	750-155
2.4 EFI	---	(Tous/All)	700-205	725-157	750-157
XR-4	---	B242885 & +	700-205	725-157	750-157
250	(3.0L) EFI	OG129222 & +	700-155	725-155	750-155
OMC					
2	1985-90	JR. COLT	700-325	---	---
4	1976-80	---	700-325	---	---
4	1980-97	DELUXE	700-265	---	---
4.5	1980-97	---	700-265	---	---
6	1979	---	700-325	---	---
6	1984-97	---	700-265	---	---
6	1998 & +	4 Stroke	700-265	---	---
8	1986-97	2 Stroke	700-265	---	---
8	1996-97	4 Stroke	700-290	---	750-290
9.5	1964-73	---	700-280	---	---
9.9	1974-97	---	700-290	---	750-290
9.9	1994-97	4 Stroke	700-290	---	750-290
15	1956-73	---	700-275	---	---
15	1974-97	---	700-290	---	750-290
15	1994-97	4 Stroke	700-290	---	750-290
20	1966-78	---	700-275	---	---
20	1981-84	---	700-295	---	---
20	1985-97	---	700-295	---	750-250
25	1979-84	---	700-295	---	---
25C	1983-91	---	700-295	---	---
25	1985-97	---	700-295	---	750-250
25D	1993-95	---	700-255	---	---
28	1987-96	---	700-295	---	---
28	1978 & +	---	700-295	---	---
28	1995-96	Jet	700-255	---	---
30	1984-97	---	700-295	---	750-250
30	1984 & +	---	700-295	---	---
30	1983 & +	---	700-295	---	---
35	1980-97	---	700-295	---	750-250
35	1996	Jet	700-255	---	---
40	1960-70	---	700.320	---	---
40	1984-85	---	700-305	---	---
40	1986-88	---	700-250	---	---
40	1989-98	---	700-255	---	---
45	1993-94	---	700-250	---	---
45 / 55	1985	COMM.	700-305	---	---
48	1987-88	---	700-250	---	---
48	1989-96	---	700-255	---	---
50	1979-85	---	700-305	---	---
50	1986-88	---	700-250	---	---
50	1989-98	---	700-255	---	---
50 / 55	1968-78	---	700.320	---	---
55	1979-85	---	700-305	---	---
55C	1993-94	---	700-250	---	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
OMC					
60	1986-94	---	700-300	---	750-251
60	1980-85	---	700-305	---	---
60SST	1989	---	700-300	---	750-251
65C	1984-94	---	700-300	---	750-251
65	1994	Jet	700-310	---	750-255
70	1974-78	---	700-315	---	---
70	1979-94	---	700-300	---	750-251
75	1979-88	---	700-300	---	750-251
1.6L	1982-94	---	700-310	725-310	750-255
80	1993-96	---	700-310	725-310	750-255
85	1978-81	---	700-285	---	750-254
85TTL	1993-95	---	700-310	725-310	750-255
88	1987-96	---	700-310	725-310	750-255
90*	1982-97	---	700-310	725-310	750-255
90	1995 & +	SL,DI	700-310	---	---
100	1979-97	---	700-310	725-310	750-255
100C	1984-97	---	700-310	725-310	750-255
105	1998-2001	COMM.	700-310	---	---
105	1994-97	Jet	700-310	725-310	750-255
110	1986-93	---	700-310	725-310	750-255
112	1994-96	---	700-310	725-310	750-255
115	1977	25''	700-285	---	750-254
115	1978	---	700-285	---	750-254
115	1979-97	---	700-310	725-310	750-255
115	1995 & +	SL,DL	700-310	---	---
120	1985-94	---	700-310	725-310	750-255
120	1993-2000	25''	700-310	---	---
125	1994-95	---	700-310	725-310	750-255
125	1993-94	ESX 25''	700-310	---	---
130	1994-97	---	700-310	725-310	750-255
130	1994-2000	25''	700-310	---	---
135	2001	25''	700-310	---	---
140	1977-78	---	700-285	---	700-254
140	1979-94	---	700-310	725-310	750-255
140	1994-2000	25''	700-310	---	---
150	1979-97	---	700-310	725-310	750-255
150	1993 & +	20''	700-310	---	---
150	1996-98	EL 20	700-310	---	---
150	1994-98	SL 20	700-310	---	---
150	1993 & +	25''	700-310	---	---
150	1997 & +	DI	700-310	---	---
155	1984 & +	---	700-310	725-310	750-255
175	1976-78	---	700-285	---	750-254
175	1979-97	---	700-310	725-310	750-255
175	1996-98	EL 20''	700-310	---	---
175	1994-98	SL 20''	700-310	---	---
175	1997 & +	DI	700-310	---	---
185	1984-94	---	700-310	725-310	750-255
200	1976-78	---	700-285	---	750-254
200	1979-97	---	700-310	725-310	750-255
200	1990	COMM.	700-310	---	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
OMC					
225	1986-97	---	700-310	725-310	750-255
225	1993 & +	20	700-310	---	---
225	1993-97	25 & 30	700-310	---	---
235	1979-85	---	700-310	725-310	750-255
250	1993-95	---	700-310	725-310	750-255
275	1985 & +	---	700-310	725-310	750-255
300/ 3.6L	1985-95	---	700-310	725-310	750-255
2.3L	1982-94	---	700-310	725-310	750-255
V4	1993 & +	LOOP 20	700-310	---	---
V6-V8	1993 & +	25'' 30''	700-310	---	---
TOHATSU/NISSAN					
25	2003	---	700-360	---	---
30	2003	---	700-360	---	---
40	2003	---	700-355	---	---
40	2004	---	700-360	---	---
50	---	---	700-355	---	---
60	2003	---	700-350	---	---
70	---	---	700-350	---	---
90	1996	3 Cyl.	700-350	---	---
120	2003	4 Cyl.	700-350	---	---
140	---	4 Cyl.	700-350	---	---
YAMAHA					
6 / 8	1984-2002	---	700-405	---	---
T8	2001-02	---	700-400	---	---
9.9	1984-90	---	700-435	---	---
9.9 & 15	1984-95	---	700-435	---	---
9.9	1996-2004	---	700-400	---	---
F/T 9.9	1985-90	---	700-435	---	---
T 9.9	1991-96	---	700-435	---	---
15	1984-95	---	700-435	---	---
15	1996-2004	---	700-400	---	---
F15	1996-2004	---	700-400	---	---
25	1984-85	---	700-410	---	---
25	1986-87	---	700-410	---	---
25	1996-2002	---	700-415	---	---
C25 (695)	1990-94	---	700-410	---	---
C25	1990-97	---	700-410	---	---
CV25	1990	---	700-410	---	---
F25	1998-2004	---	700-415	---	---
T25	2001-04	---	700-415	---	---
30	1984-85	---	700-410	---	---
30	1986	---	700-410	---	---
30	1987-95	---	700-320	---	---
C30 (689)	1990-92	---	700-410	---	---
CV30	1989	---	700-410	---	---
F30	2001-04	---	700-415	---	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
YAMAHA					
40	1984-91	---	700-415	---	---
40	1995-2004	---	700-415	---	---
C40 (6R6)	1990-95	---	700-320	---	---
C40	1992-97	---	700-320	---	---
C40	1997-2002	---	700-420	---	---
CV40	1990	---	700-320	---	---
F40	1999	---	700-420	---	---
F40	2000-04	---	700-415	---	---
P40	1998	---	700-420	---	---
F40 2.6L	1999	---	700-420	---	---
50	1984-94	---	700-415	---	---
50	1995-2004	---	700-420	---	---
C50	1999-2001	---	700-420	---	---
F50	1999-2003	---	700-420	---	---
PRO50	1987-94	---	700-415	---	---
50 & PRO50	1992-94	---	700-415	---	---
P50	1991-93	---	700-415	---	---
P50	1995-96	---	700-420	---	---
50 Jet	1986-89	---	700-415	---	---
T50	1996	---	700-420	---	---
T50	1996-2002	---	700-420	---	---
C55 (697)	1989-91	---	700-420	---	---
C55,Drive1	1991-94	---	700-420	---	---
CV55,Drive1	1989	---	700-420	---	---
C55,Drive2	1991-94	---	700-420	---	---
CV55,Drive2	1989	---	700-420	---	---
P60 (6H2)	1991-95	---	700-420	---	---
C60	1996-2001	---	700-420	---	---
E60	1995-2000	---	700-420	---	---
F60	2002-03	---	700-420	---	---
P60	1991-99	---	700-420	---	---
70	1984-91	---	700-420	---	---
70 (6H3)	1984-95	---	700-420	---	---
C70	2000-01	---	700-420	---	---
C75 (692)	1994-96	---	700-425	725-432	750-432
E75	1995-2000	---	700-425	---	---
P75	1997	---	700-425	---	---
C80	1997	---	700-425	---	---
85	1985	---	700-425	---	---
CV85 (688)	1989-90	---	700-425	---	---
CV85	1989-91	---	700-425	725-432	750-432
C85	1989-97	---	700-425	725-432	750-432
C85 (688)	1991	---	700-425	---	---
C85 (688)	1992-95	---	700-425	---	---
90	1984-96	---	700-425	725-432	750-432
90	1984-2002	---	700-425	---	---
90 (6H1)	1984-91	---	700-425	---	---
90 (6H1)	1992-95	---	700-425	---	---
90 Jet	1986-89	---	700-425	---	---
C90	1997-2001	---	700-425	---	---
B90	1997-99	---	700-425	---	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
YAMAHA					
F115/LF115	2000-02	---	700-430	---	---
115 (6N6)	1989-94	---	700-430	---	---
115 (6N6)	1984-92	---	700-430	---	---
115 (6N6)	1993-95	---	700-430	---	---
C115 (6E5)	1991-92	---	700-430	---	---
C115 (6E5)	1993-95	---	700-430	---	---
C115 (6E5)	1994	---	700-430	---	---
P115 (62A)	1993-95	---	700-430	---	---
130 (6L1)	1988-89	---	700-430	---	---
130 (6N7)	1990-92	---	700-430	---	---
130 (6N7)	1993-95	---	700-430	---	---
L130 (6L6)	1989-92	---	700-430	---	---
L130 (6N4)	1993-96	---	700-430	---	---
L150	1986-91	---	700-430	---	---
L150 (6R0)	1992-99	---	700-430	---	---
150 (6G4)	1984-91	---	700-430	---	---
150 (6R2)	1992-99	---	700-430	---	---
150 (6R2)	1992-95	---	700-430	---	---
P150 (6N6)	1986-91	---	700-430	---	---
P150 (6N9)	1992-95	---	700-430	---	---
PX150	1999	---	700-430	---	---
SX150	1999-2002	---	700-430	---	---
L150 (6K0)	1986-89	---	700-430	---	---
L150 (6R0)	1992-95	---	700-430	---	---
V150	2000-02	---	700-430	---	---
VZ150	2001-02	---	700-430	---	---
Z150/LZ150	2001-02	---	700-430	---	---
175 (6GS)	1984-89	---	700-430	---	---
175 (6G5)	1984-91	---	700-430	---	---
175 (6R3)	1990-91	---	700-430	---	---
175 (6R3)	1992-95	---	700-430	---	---
175 (6R3)	1992-2000	---	700-430	---	---
P175 (62H)	1994-95	---	700-430	---	---
P175 (62H)	1994-99	---	700-430	---	---
150/ 175/ 200ETLN	1984	---	700-430	---	---
VZ175	2001-02	---	700-430	---	---
Z175	2001-02	---	700-430	---	---
200 (6G6)	1984-91	---	700-430	---	---
200 (6R4)	1990-91	---	700-430	---	---
200 (6R4)	1992-95	---	700-430	---	---
200 (6R4)	1992-99	---	700-430	---	---
F200/ LF200	1992-99	---	700-430	---	---
L200 (6K1)	1986-89	---	700-430	---	---
L200 (6R1)	1990-91	---	700-430	---	---
L200 (6R1)	1992-95	---	700-430	---	---
LX200	1999-2002	---	700-430	---	---
P200 (61H)	1991	---	700-430	---	---
P200 (61H)	1992-95	---	700-430	---	---
SX200	1999-2002	---	700-430	---	---
V200	1998-99	---	700-430	---	---
VZ200	2001-02	---	700-430	---	---

REFROIDISSEMENT - COOLING

HP	Année/Year Modèle/Model	#Série / Serial#	Hélice / Impeller	Ens . Service / Service Kit	Ens. Complet / Complete Kit
YAMAHA					
LX225/ SX225	2000-02	---	700-430	---	---
Z200/ LZ200	2000-02	---	700-430	---	---
225 (6R5)	1990-91	---	700-430	---	---
225 (6R5)	1992-93	---	700-430	---	---
225 (62J) L225	1994-95	---	700-430	---	---
F225/ LF225	2002	---	700-430	---	---
V225	1998-99	---	700-430	---	---
VX225	2000-02	---	700-430	---	---
250 (61A) L250	1990-95	---	700-430	---	---
L250/ S250	1997-99	---	700-430	---	---
VX250	2002	---	700-430	---	---
Pro V150 6J9)	1986-89	---	700-430	---	---
Pro V150D (6N9)	1990	---	700-430	---	---
Excel (6K7)	1987-89	---	700-430	---	---
Special(6G7)	1984-86	---	700-430	---	---