

SYSTÈME ÉLECTRIQUE - 1 - ELECTRICAL SYSTEM

INDUITS - COILS

| Modèle / Model | Année / Year | # Origine / OEM # | Type | # Pièce / Part # |
|--|--------------|---------------------------------------|--------------|------------------|
| Arctic Cat / Kawasaki | | | | |
| Tous les / All 292 single cyl. KT 150 Kaw. Engine 3000-179, 3000-063 | | | Lighting | LC1103 |
| Cheetah | 1972 | 3000-178 | Exciter | LC1095 |
| Cheetah 340 | 1975 | 3001-053 | Exciter | LC110401 |
| El Tigre | 1973-74 | 3001-053 | Exciter | LC110401 |
| El Tigre 250 | 1973 | 3001-053 | Exciter | LC110401 |
| El Tigre 295 | 1974 | 3001-053 | Exciter | LC110401 |
| El Tigre 340 | 1973-74 | 3001-053 | Exciter | LC110401 |
| El Tigre 340 | 1975 | 3001-129 | Exciter | LC110402 |
| El Tigre 400 | 1973-74 | 3001-129 | Exciter | LC110402 |
| El Tigre 440 | 1973-75 | 3001-129 | Exciter | LC110402 |
| Lynx | 1971-72 | 3000-179, 3000-063 | Lighting | LC1103 |
| Panther | 1960-72 | 3000-179, 3000-063 | Lighting | LC1103 |
| Panther | 1972 | 3000-178 | Exciter | LC1095 |
| Panther | 1974-75 | 3001-053 | Exciter | LC110401 |
| Puma | 1972 | 3000-178 | Exciter | LC1095 |
| VIP | 1974 | 3001-129 | Exciter | LC110402 |
| Z | 1975 | 3001-129 | Exciter | LC110402 |
| Arctic Cat / Suzuki | | | | |
| Tous les modèles F/C Models | 1977-84 | 3002-576 | Timer sensor | LC1096 |
| Cheetah | 1975 | 3001-530 | Lighting | LC1108 |
| Cross Country | 1976 | 3003-398 | Coil B | LC1098 |
| El Tigre 400/440 | 1973-75 | 3001-130 | Pulser | LC1101 |
| Jag | 1975 | 3001-530 | Lighting | LC1108 |
| Jag F/A | 1978-80 | 3003-398 | Coil B | LC1098 |
| Lynx | 1975 | 3001-530 | Lighting | LC1108 |
| Lynx 2000T | 1978 | 3003-398 | Coil B | LC1098 |
| Pantera | 1975 | 3001-530 | Lighting | LC1108 |
| Pantera | 1978 | 3003-398 | Coil B | LC1098 |
| Bosch | | | | |
| --- | --- | 1.214.210.182 | Lighting | LC100 |
| --- | --- | 1.214.210.107 | Lighting | LC101 |
| --- | --- | 121421062 | Lighting | LC104 |
| --- | --- | 121421060 | Lighting | LC103 |
| 370, 401, 440, 500, 601 | 1970-72 | 1214210184 | Generator | LC408102 |
| 640, 641, 680, 775, 776 | 1970-72 | 1214210184 | Generator | LC408102 |
| Kawasaki | | | | |
| Intruder | 1980 | 21049-3001 | Generator | LC108305 |
| Invader | 1980-81 | 21049-3001 | Generator | LC108305 |
| Moto-Ski | | | | |
| Futura 444 L.C., 500 L/C | 1978-81 | 420.8658.22 | Lighting | LC408704 |
| Grand Prix Special, MX | 1979-81 | 420.8658.22 | Lighting | LC408704 |
| Mirage I, II, SP | 1980-81 | 420.8658.22 | Lighting | LC408704 |
| Sonic | 1977-78 | 420.8658.25 | Lighting | LC408701 |
| Sonic 250, 340 | 1976 | 420.8658.25 | Lighting | LC408701 |
| Futura 400,E | 1977-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Futura 440 | 1975-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Futura 440E | 1976-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Futura 444 L.C. | 1978-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Futura 500,E | 1980-81 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Futura 500 L/C. | 1980 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Grand Prix Special | 1979-81 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Mirage II, E, Special | 1980-81 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |

SYSTÈME ÉLECTRIQUE - 1 - ELECTRICAL SYSTEM

INDUITS - COILS

| Modèle / Model | Année / Year | # Origine / OEM # | Type | # Pièce / Part # |
|----------------------------|--------------|--|----------|------------------|
| Moto-Ski / Bosch | | | | |
| Nuvik 300 | 1976-77 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Nuvik 340,E | 1976-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Nuvik 440,E | 1977 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Spirit 247 | 1976 | 420.8643.21 | Lighting | LC100 |
| Polaris | | | | |
| Apollo 250, 340 | 1979-80 | 3081130 | Lighting | LC208405 |
| Cobra | 1978-79 | 3081130 | Lighting | LC208405 |
| Cobra 340 | 1978-79 | 3081130 | Lighting | LC208405 |
| Cobra 340, 440 | 1978-79 | 3081130 | Lighting | LC208405 |
| Colt 250 | 1978 | 3081130 | Lighting | LC208405 |
| Colt 250SS, 295, 295SS | 1974-76 | 3081130 | Lighting | LC208405 |
| Colt 340SS | 1974-76, 78 | 3081130 | Lighting | LC208405 |
| Cutlass 340 | 1981 | 3081130 | Lighting | LC208405 |
| Electra 340, 440 | 1980-81 | 3081130 | Lighting | LC208405 |
| Galaxy 340, 440 | 1980-81 | 3081130 | Lighting | LC208405 |
| Rupp / Tohatsu | | | | |
| 292, 340, 400, 400ZS | 1973-81 | 20578 | Pulser | LC108802 |
| 292, 340, 400, 440 | 1973-81 | 20579 | External | LC108801 |
| Scorpion / Bosch | | | | |
| Moteurs Cuyuna Engines | 1978-79 | 1.214.210.091 | Lighting | LC1070 |
| Moteurs Cuyuna Engines | 1978-79 | 1.214.210.394 | Lighting | LC1071 |
| Moteurs Cuyuna Engines | 1978-79 | 1.214.210.282(01-143-32) | Lighting | LC134 |
| TK, Whip | 1980-81 | 1.214.210.091 | Lighting | LC1070 |
| TK, Whip | 1980-81 | 1.214.210.394 | Lighting | LC1071 |
| TK, Whip | 1980-81 | 1.214.210.282(01-143-32) | Lighting | LC134 |
| Ski-Doo | | | | |
| Alpine 640ER | 1976-82 | 420.8658.22 | Lighting | LC408704 |
| Blizzard 5500 MX | 1979-81 | 420.8658.22 | Lighting | LC408704 |
| Blizzard 5500, MX | 1979-81 | 420.8658.22 | Lighting | LC408704 |
| Citation 3500, 4500, SS | 1980-81 | 420.8658.22 | Lighting | LC408704 |
| Everest 440 | 1975 | 420.8658.25 | Lighting | LC408701 |
| Everest L/C, 440, 500, L/C | 1978-80 | 420.8658.22 | Lighting | LC408704 |
| Nordik | 1981 | 420.8658.22 | Lighting | LC408704 |
| TNT RV 250 | 1976 | 420.8658.25 | Lighting | LC408701 |
| TNT RV 340 | 1976-77 | 420.8658.25 | Lighting | LC408701 |
| Ski-Doo / Bosch | | | | |
| Alpine 640ER | 1975, 78-82 | 410.7002.00, 1.214.210.282 (01-143-32) | Lighting | LC134 |
| Alpine 640R | 1976-77 | 410.7002.00, 1.214.210.282 (01-143-32) | Lighting | LC134 |
| Blizzard 5500 | 1979-81 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Blizzard MX | 1981 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Citation 4500, E, SS | 1980-81 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Elan 250 | 1975-76 | 420.8643.21 | Lighting | LC100 |
| Elite 450 L.C. | 1978-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Everest 340,E | 1977-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Everest 440 | 74,77-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Everest 440E | 1977-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Everest 444 L.C. | 1978-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Everest 500 L.C. | 1980 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Everest 500,E | 1980-81 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Nordik | 1981 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |

SYSTÈME ÉLECTRIQUE - 1 - ELECTRICAL SYSTEM

INDUITS - COILS

| Modèle / Model | Année / Year | # Origine / OEM # | Type | # Pièce / Part # |
|------------------------|--------------|---------------------------------------|----------|------------------|
| Ski-Doo / Bosch | | | | |
| Olympique 300 | 1975, 1978 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Olympique 300E | 1975 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Olympique 300T | 1976-77 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Olympique 300TE | 1976 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Olympique 340 | 1975-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Olympique 340E | 1975-79 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Olympique Plus 440 | 1977 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| TNT 340, 440 | 1974 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| TNT Everest 440, E | 1976 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| TNT F/A 340 | 1978 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| TNT F/C 340,E | 1975-76 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| TNT F/C 440 | 1975, 77-78 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| TNT F/C 440E | 1975 | 410.7002.00,1.214.210.282 (01-143-32) | Lighting | LC134 |
| Yamaha | | | | |
| EC 540 | 1979-86 | 8H8-85513-20-00 | Lighting | LC608505 |
| EC 540 | 1984-86 | 8V0-85514-20-00 | Lighting | LC608506 |
| EL 433 | 1972-73 | 838-81312-20-00, 839-81312-20-00 | Charging | LC608508 |
| ET 300, 340 | 1979-86 | 8F2-85513-10-00, 8K4-85513-10-00 | Lighting | LC608504 |
| ET 340 | 1980 | 8H8-85513-20-00 | Lighting | LC608505 |
| ET 340 | 1984-86 | 8G8-85513-20-00 | Lighting | LC608507 |
| EW 433, 643 | 1972-73 | 838-81312-20-00, 839-81312-20-00 | Charging | LC608508 |
| EX 570 | 1987-88 | 8H8-85513-20-00 | Lighting | LC608505 |
| GP 338, 433, 643 | 1972-76 | 838-81312-20-00, 839-81312-20-00 | Charging | LC608508 |
| GS 340 | 1976 | 838-81312-20-00, 839-81312-20-00 | Charging | LC608508 |
| PR 440 | 1976 | 838-81312-20-00, 839-81312-20-00 | Charging | LC608508 |
| PZ 440, 480 | 1984-89 | 8H8-85513-20-00 | Lighting | LC608505 |
| PZ 480 | 1985-89 | 8V0-85514-20-00 | Lighting | LC608506 |
| SL 338, 433 | 1972-74 | 838-81312-20-00, 839-81312-20-00 | Charging | LC608508 |
| SM 292 | 1973-74 | 838-81312-20-00, 839-81312-20-00 | Charging | LC608508 |
| SR 540 | 1980-89 | 8F2-85513-10-00, 8K4-85513-10-00 | Lighting | LC608504 |
| SR 540 | 1984-89 | 8V0-85514-20-00 | Lighting | LC608506 |
| SRX 440 | 1977-81 | 8F2-85513-10-00, 8K4-85513-10-00 | Lighting | LC608504 |
| SS 440 | 1980-85 | 8F2-85513-10-00, 8K4-85513-10-00 | Lighting | LC608504 |
| SS 440 | 1985 | 8V0-85514-20-00 | Lighting | LC608506 |
| TL 433 | 1974 | 838-81312-20-00, 839-81312-20-00 | Charging | LC608508 |
| TW 433 | 1974 | 838-81312-20-00, 839-81312-20-00 | Charging | LC608508 |
| VMX 540 | 1983-88 | 8F2-85513-10-00, 8K4-85513-10-00 | Lighting | LC608504 |
| XL 540 | 1985-89 | 8V0-85514-20-00 | Lighting | LC608506 |
| XL 540 | 1985-89 | 8H8-85513-20-00 | Lighting | LC608505 |

SYSTÈME ÉLECTRIQUE - 1 - ELECTRICAL SYSTEM

INDUITS - COILS

| | | | | | | |
|--|--|--|--|---|--|--|
|  LC100 |  LC101 |  LC103 |  LC104 |  LC1070 |  LC1071 |  LC108305 |
|  LC108801 |  LC108802 |  LC1095 |  LC1096 |  LC1098 |  LC1101 |  LC1103 |
|  LC110401 |  LC110402 |  LC1108 |  LC134 |  LC208405 |  LC408102 |  LC408701 |
|  LC408704 |  LC608504 |  LC608505 |  LC608506 |  LC608507 |  LC608508 | |